



NOTES:
 - TEMPERATURE SENSOR TO BE MOUNTED IN OPEN AIR, OUT OF DIRECT SUNLIGHT, AND AWAY FROM HEATING AND COOLING EQUIPMENT
 - ADDITIONAL THERMOMETERS OR BAROMETERS TO BE WIRED IN PARALLEL

UNLESS OTHERWISE SPECIFIED: ALL DIMENSIONS IN INCHES	
TOLERANCES ON DECIMAL DIMENSIONS: .X ± .031 .XX ± .01 .XXX ± .005	
DO NOT SCALE DRAWING	
MATERIAL	NONE
TREATMENT	NONE
FINISH	NONE

APPROVALS	DATE
DRAWN THA	7-13-2004
ENGINEER THA	

TITLE WIRING DIAGRAM CTRL-TBX			
SIZE A	SCALE: NONE	DWG. NO. A-5661	REV.
M:\INVENTOR\DRAWINGS\A-5661.idw			SHEET 1